

			PRC/DeSoto	Flamemaster Chemseal	Pro-Seal	Other
	MIL-S-38249 TYI / AMS3374 TY 4	Firewall sealant	PR812	CS1900	PS700	
	MIL-S-38228 TYII / DMS1819	Environmental sealant	PR340	CS2415	PS895	
	MIL-S-7502 obsolete Replaced by MIL-S-8802	Integral fuel tank and fuel cells	PR1221B	CS3201	PS707	EC1239B
	MIL-S-7124	Aircraft structure polysulfide	PR1221	CS3201 A&B	PS894A/B	EC1063B
	MIL-S-11031B	Sealing compound Class B black	PR383B	CS3202B	PS247B	EC801B
	MIL-PRF-81733 & BMS5-95	Corrosion Inhibitive			PS870 A&B	
	MIL-S-8802 TYPE II / AMS-S-8802	Aircraft fuel tank sealant	PR1440 A&B	CS3204 A&B		
	MIL-S-8802F TYPE I DELETED	Aircraft fuel tank sealant	PR1422 A&B			
	BMS5-44L	Aircraft Fuel Tank Sealant			PS890 A&B	
	MIL-S-83430 CANCELED	Aircraft fuel tank sealant Higher temp resistance	PR1750	CS5500	PS899	
		Aircraft fuel tank sealant quick repair	PR1435	CS3204B-1/4		
	PENDING	Quick repair windshield sealant	PR1829	CS5447		
	DPM 5941 HEROUX	Quick repair sealant		CS3206B-1/6	PS860B-1/6	
	MIL-S-4383C	Fuel tank sealing topcoat Buna-N type	PR1005L	CS3600		
	MIL-PRF-8516G	For electric connections and systems	PR1201	CS3100	PS727	
	Proposed AMS 3333	Windshield sealant	PR1425	CS3247		
	MIL-S-8784B / AMS3284	Replaced by CS3330 A&B below	PR1321 A&B	CS3300 A&B		
	MIL-S-8784B / DMS2410	Access door sealant lead free	PR1428 A&B	CS3330 A&B		
	AMS 3265 / DMS 2013	Corrosion inhibitive	PR1775	CS5500ci		
	AMS 3281	Fuel tank sealant	PR1776	CS5530/5540		
	MIL-S-29574TYI / AMS 3277 TYI	Fast cure - flight line repair	PR1826	CS5306/5310		
	MIL-S-29574TYII / AMS 3277 TYII	Fast cure - flight line repair	PR1828	CS5307/5311		